



Model 3810 CL

AC/DC Clamp Meter



CE

3810 CL

3810CL TRUE RMS AC/DC Clamp Meter

- Full auto range for V.A and Ω functions.
- Data hold function freezes the reading in dimly lit or hard to reach places.
- Low battery indication.
- Built-in buzzer for continuity test.
- Safety design throughout with no exposed metal parts. Shielded banana plugs and recessed input terminals.
- Ohm function ideal for checking continuity of relays transformers and motor coils.

Accessories

Instruction manual
 Test leads
 Soft pouch
 Battery

Specifications

AC A	400A / 1000A	$\pm(1.5\%rdg+3dgt)$	40-500Hz
AC V	400V / 600V	$\pm(1.0\%rdg+3dgt)$	40-500Hz
DC A	400A / 1000A	$\pm(1.5\%rdg+3dgt)$	
DC V	400V / 600V	$\pm(0.75\%rdg+3dgt)$	
Ω	400 Ω / 2000 Ω	$\pm(1.0\%rdg+3dgt)$	
Flashlight	—		
LCD backlight display	—		
Buzzer sounds	< 38 Ω		
Conductor size	40mm Max.		
Low battery Indication			
Dimensions	255(L) \times 80(W) \times 35(D)mm		
Weight (battery included)	Approx. 420g		
Power source	9V(6F22) \times 1		
Safety standard	EN 61010-1 CAT III 600V EN 61010-2-32 EN 61010-2-33		